



CONDITION REPORT

2011 Toyota Venza BASE PREMIUM






INV # ABF4467

VIN: 023132

ARRIVAL DATE: 11/4/2014

UNIT # 1011205

CONSIGNOR:



VEHICLE IDENTIFICATION

VEHICLE:	2011 Toyota Venza BASE PREMIUM	INSPECTION LOCATION:	Vancouver, BC
VIN #:	4T3BA3BB3BU023132		
ODOMETER:	27,253 KM Digital	ODOMETER CONDITION:	OK
# OF DOORS	4	# OF PASSENGERS:	5
EXT. COLOR:	Black	BODY STYLE:	Station Wagon
# OF KEYS:	2	# OF REMOTES:	2
		HEAVY DUTY:	NO
ENGINE:	4 Cylinder, 2.7L, Gasoline Fuel	WHEEL BASE:	
TRANSMISSION:	Transmission-Auto-6 Spd		
DRIVE TRAIN:	AllWheelDrive		



CONDITION REPORT

VIN: 023132

2011 Toyota Venza BASE PREMIUM

ARRIVAL DATE: 11/4/2014

INV # ABF4467

UNIT # 1011205

CONSIGNOR:

INTERIOR SPECIFICATIONS			
INT. COLOR:	Other	FRONT SEATS:	Individual
FLOOR:	Carpet	REAR SEATS:	Split Folding
		SEAT TYPE:	Leather
INTERIOR OPTIONS			
<p>Driver & front passenger dual-stage air bags, Front seat-mounted side air bags, Front & rear side curtain air bags, Dual zone auto climate control, AM/FM stereo w/CD/MP3 player -inc: XM satellite radio, aux input jack, USB audio input, Auto Sound L, Anti-lock Braking System (ABS) w/Electronic Brake Force Distribution (EBD), Brake Assist (BA), Front ventilated & rear solid disc brakes, Cruise control, Rear window defroster w/timer, Child safety rear door locks, All wheel drive, 2.7L DOHC 16-valve dual VVT-i I4 engine, Carpeted floor mats, Front captain seats -inc: 8-way pwr driver seat w/lumbar support, active front headrests w/whiplash , Rear 60/40 split bench seat -inc: fold-down seat back, vertical headrests adjustment, remote release, Pwr rack & pinion steering, 3-spoke tilt & telescopic steering wheel w/audio controls, 6-speed automatic transmission w/OD -inc: Super Electronically Controlled (Super ECT), lock-up torque, Pwr windows w/auto up/down for all windows, 12V aux pwr outlets -inc: (2) front, (1) rear, Auto-dimming rearview mirror w/compass, Illuminated dual vanity mirrors, Map lamps, Warnings -inc: trans fluid temp warning, low fuel & washer fluid, door ajar, tire pressure monitorin, Optitron instrumentation -inc: tachometer, water & outside temp, dual trip odometer, multi info disp, Garage door remote, Bluetooth capability, Front passenger air bag status indicator, Driver knee airbag, Airbags Curtain, Airbags Dual Side, Airbags Front Dual, Cargo Cover, Floor Mats Carpet, Floor Mats Oem, Owners Manual, ABS, AWD, Air Conditioning, Power Brakes, Power Door Locks, Power Mirrors, Power Steering, Power Windows, Tilt, Heated Seats Dual, Power Heated Mirrors, Power Seat Driver, Power Sunroof, Rear Headrests, Rear View Mirror Compass\Temp, Rear Window Defogger, Rear Wiper, Steering Wheel Stereo Controls, Auxiliary Audio Input, CD OEM, Cell Phone Hookup, Hands-Free Communications System, Radio OEM, Satellite Radio, Power Rear Vents, Rear Air Conditioning, Rear Heat</p>			
EXTERIOR OPTIONS			
<p>Folding pwr heated mirrors, Compact spare tire, 19" aluminum alloy wheels w/wheel locks, Variable-intermittent windshield wipers, Fog lamps, Rear privacy glass, Rear spoiler w/LED stop lamp, Fog Lights OEM, Keyless Entry Remote, Rear Bumper Reverse Camera, Rear Spoiler</p>			
MECHANICAL DETAILS			
<p>Unit has NOT been mechanically inspected. Unit runs and drives Exception as noted below. WESTERN CANADA REMARKETING INC assumes no responsibility for mechanical condition. Sold under Green Light. See arbitration policy for light definitions.</p>			



CONDITION REPORT

VIN: 023132









2011 Toyota Venza BASE PREMIUM

ARRIVAL DATE: 11/4/2014

INV # ABF4467

UNIT # 1011205

CONSIGNOR:

INTERIOR DAMAGE			
Location	Description	Repair Cost	Images
Other - Headliner	OTHER DAMAGES - STAINED	\$0.00	
Other - All Interior	NORMAL WEAR AND TEAR	\$0.00	
		Total Interior Repair Cost:	\$0.00
EXTERIOR DAMAGE			
Location	Description	Repair Cost	Images
Front Door Driver - Panel	SCRAPE	\$0.00	
Rear Door Driver - Panel	MULTIPLE SCRATCHES	\$0.00	
Rear Bumper - All	MULTIPLE CHIPS	\$0.00	
Rear Door Handle\Lock Psg - Panel	OTHER DAMAGES - MULTIPLE SCRATCHES AROUND DOOR HANDLE. SIMILAR ON MULTIPLE PANELS	\$0.00	
Front Door Psg - Panel	OTHER DAMAGES - MULTIPLE CHIPS AND SCRATCHES SIMILAR ON MULTIPLE PANELS	\$0.00	
Roof - All	MULTIPLE CHIPS	\$0.00	
Other - Multiple Panels	NORMAL WEAR AND TEAR	\$0.00	
		Total Exterior Repair Cost:	\$0.00



CONDITION REPORT

VIN: 023132

2011 Toyota Venza BASE PREMIUM

ARRIVAL DATE: 11/4/2014

INV # ABF4467

UNIT # 1011205

CONSIGNOR:

TIRES						
	MAKE	SIZE	TREAD	BALANCE	WEAR	WHEEL TYPE
Driver Front	Bridgestone	19	7 / 32	50%	NORMAL	Alloy: Natural
Driver Rear	Bridgestone	19	8 / 32	60%	NORMAL	Alloy: Natural
Psg Rear	Bridgestone	19	8 / 32	60%	NORMAL	Alloy: Natural
Psg Front	Bridgestone	19	6 / 32	40%	NORMAL	Alloy: Natural
SEASONAL TYPE:	All-Season					
SPARE INFO:	Spare present and not in use					
SPARE SIZE:	Compact	SPARE CONDITION:		USED		
SPARE LOCATION:	Spare					
SPARE WHEEL TYPE:	Steel					

DECLARATIONS	
VEHICLE LIGHT STATUS:	GREEN
DECLARATION CHECK:	EX-LEASE

REGISTRATION AND DOOR STICKER INFORMATION			
GVW FT:		GVW TOTAL:	
GVW RR:			
MANUFACTURE DATE:	01/2011	ORIGIN:	
REGISTRATION:	Yes	REG TYPE:	
PROV. OF REGISTRATION:	British Columbia	LICENSE PLATE:	371TKX
VINSTICKER CONDITION:	Present		